## North America Emission Control Area Fuel Oil Non-Availability Report
## ECA0100
## 1 2
##
##(Include Double Pound for comments, not form fields)
##Report Form ID Ship Operator Name

Fleet Management, Ltd.

_	_	_		
٦ ,	4	5	6 7	
J .	•	J	,	

Vessel Name Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice

MV SUZUKA EXPRESS PANAMA 9448073 4-Aug-18 Vessel at sea

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption

San Juan, Puerto Rico

Saint John, Antigua

Manzanillo,Panama

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA

BOMIN NA 9-Aug-18

14	15	16

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion

7:00 2.57% 6

Name of First POC

Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC?

San Juan, Puerto, Rico NA

NA

20	21	22

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

NA Port EverGlades NA

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

NA NA

25 26

27

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

12-Aug-18

0:01 YES

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms?

2 NA

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail

NIL CAPT.M.SATHYA <u>msathya@fleetship.com</u>

Designated Corporate Official Phone Number

(852) 93713909

35
Description of Actions to Achieve Compliance
Supplying Fuel Pump spares on arrival San Juan and complete overhaul of all fuel pumps will completed prior vessels dep